


# SLHM 50 Accessories

(included with machine)

NO.	ACCESSORIES	Qty
1	2.5MM HEX WRENCH	1
2	5MM HEX WRENCH	1
3	6MM HEX WRENCH	1
4	SAFETY CHAIN	1
5	THREE HANDLES	3
6	COOLANT	1
7	MT2 -19MM ARBOR	1
8	SPANNER	1
9	INSTRUCTION MANUAL	1



## SLHM50 Spare Parts schematic

